RESPONSE UNDER 37 C.F.R. § 1.111 Attorney Docket No.: Q68419

Appln. No.: 10/070,379

## **AMENDMENTS TO THE DRAWINGS**

The attached four (4) sheets of drawings (Figs. 5, 7, 9 and 17) includes the following changes:

In Fig. 5, (c) is corrected to (a) and (d) is corrected to (b).

In Fig. 7, "Vin" is added.

In Fig. 9(a), "136" is corrected to "137" and "137" is corrected to "136".

In Fig. 17, "Prior Art" label is added.

Attachment: Four (4) Annotated Marked-Up Drawings

Four (4) Replacement Sheets




Annotated Sheet Showing Change(s)
akashi SHIMADA, et al.
cocket No: Q68419 USSN: 10/070,379
"STRUCTURE INSPECTION
APPARATUS"
(202) 293-7060 5/15




Fig. 5





b (d)





Takashi SHIMADA, et al.

cket No: Q68419 USSN: 10/070,379

STRUCTURE INSPECTION

APPARATUS" (202) 293-7060

6/15

Fig. 6





Fig. 7






Ainotated Sheet Showing Change(s)
Takashi SHIMADA, et al.
ocket No: Q68419 USSN: 10/070,379
STRUCTURE INSPECTION
APPARATUS"
(202) 293-7060 8/15

8/15

Fig. 9






Annotated Sheet Showing Change(s)
Takashi SHIMADA, et al.
Dod No: Q68419 USSN: 10/070,379
"STRUCTURE INSPECTION
APPARATUS"
(202) 293-7060 15/15

Fig. 17

Prior Art






Replacement Sheet
Takashi SHIMADA, et al.
Docket No: Q68419 USSN: 10/070,3
"STRUCTURE INSPECTION
APPARATUS"
(202) 293-7060 5/15


Fig. 5



(a)



(.b)



Replacement Sheet
Takashi SHIMADA, et al.
Doubt No: Q68419 USSN: 10/070,379
"STRUCTURE INSPECTION
APPARATUS"
(202) 293-7060 6/15

Fig. 6






Fig. 7





Takashi SHIMADA, et al.
ocket No: Q68419 USSN: 10/070,379
"STRUCTURE INSPECTION
APPARATUS"
(202) 293-7060 8/15

Fig. 9





Replacement Sheet
Takashi SHIMADA, et al.
ocket No: Q68419 USSN: 10/070,379
"STRUCTURE INSPECTION
APPARATUS"
(202) 293-7060 15/15



